




# OBERDORFER

## COOLING PUMPS FOR HELIARC WELDING



**N1000R39**


### GENERAL INFORMATION

Oberdorfer has a long history of supplying pumps to the welding machine industry. Ever since the Heliarc welding technology was developed, Oberdorfer pumps were used to circulate cooling liquid to the welder's torch.


Pump and electric motor are usually mounted on top or on the side of the coolant tank. A pressure relief valve built into the pump returns excess liquid directly to the tank rather than to the suction side of the pump, thus avoiding heat build-up in the pump.

Pump models N1000R39 and 66\* are coupled to the electric motor with a flexible coupling. The N95060GEC03 and N95060GFC01 models are close-coupled to a carbonator motor by a circular clamp arrangement, offering a space-saving, compact design alternative. Pump model N95060GE is a retrofit for Miller Electric Mfg. Co.


The reasons for the wide acceptance of Oberdorfer pumps in the welding machine industry are reliability, long service life, and ease of maintenance. The pumps depicted on this page are being produced in quantities for several welding machine manufacturers in the U.S.A.



**N1000R-66\***



**N95060GEC03  
N95060GFC01**



**N95060GE**

\*Replaces the 1000R-53

### PUMP MAINTENANCE AND REPAIR


Oberdorfer gear pumps are essentially maintenance-free. If the pump is to be shut down for an extended period of time, it should be flushed thoroughly and filled with lubricating oil.

As a general rule, it is seldom economical to repair a worn out gear pump. However, if the gear chamber inside the pump body is still in good condition, the replacement of all interior parts by use of a repair kit may restore up to 80% of the original pump performance. Repair kit numbers and parts contained in each kit are listed on the parts lists on the reverse side.

### PERFORMANCE


Pump #	RPM	PSI	0	20	40	60	80	100
N1000R39								
N95060GEC03	1725	GPM	1.5	1.4	1.3	1.2	1.1	1
N95060GFC01								
N1000R-66*	1725	GPM	2.1	1.9	1.8	1.7	1.6	1.5

### TYPICAL PUMP INSTALLATION



# OBERDORFER


## COOLING PUMPS FOR HELIARC WELDING



Pump #	Item	1	2	3	4	5	6	7	8	9	10
	Name	Screw	Body	Dowel Pin	O-Ring	Bearing	Idle Gear	Drive Gear	Bearing	Cover	Snap Ring
	Req.	6	1	2	1	2	1	1	2	1	1
N95060GEC03	5506	9301NB5N	8885	9797-033	8990	32969	32973	5024	9305NN4R	5373	
N5060GFC01	5506	9301NB5N	8885	9797-033	8990	32969	32973	5024	9305NN4R	5373	
N95060GE	5506	9301NB5N	8885	9797-033	8990	32969	32972	8990	9305NNZR	5373	

11	12	13	14	15	16	17	18	19	20	Repair Kit*
Seal Assy.	Snap Ring	Coupler	Clamp	Poppet	Spring	Adj. Screw	Washer	Lock Nut	Valve Nut	
1	1	1	1	1	1	1	2	1	1	
32584	7639	9175	8840	7640	5806	5766	6966	5774	5767	11936
32584	7639	9175	8840	7640	9718	----	----	----	----	11936
32584	7639	----	----	7640	5806	5766	6966	5774	5767	11937

\* Repair Kit contains items 3,4,5,6,7, & 10



Pump #	Item	1	2	3	4	6	8	9	10	11	13	14	15	16	17	19,20	21,22,23	Repair Kit*
	Name	Body	Cover	Carbon Bearing	Dowel Pin	O-Ring	Screw	Drive Gear	Idle Gear	Poppet	Spring	Adj. Screw	Lock Nut	Valve Nut	Fiber Washer	Seal Lip	Seal. Mech.	
	Req.	1	1	4	2	1	6	1	1	1	1	1	1	1	3	1	1	
N1000R39	9313NB2N	9314NN5L	5024	8885	9797-033	5385	32133	32118	7640	5806	5766	5774	5767	6966	5007	----	11187	
N1000R-66*	9311NB4N	9314NN5L	5024	8885	9797-033	5385	32988	32979	7640	5806	5766	5774	5767	6966	----	32584	11925	

\* Repair Kit contains items 3, 6, 9 10 & Seal.